

Indian Banks
Simonson, Richmond Co.,
Virginia.

HABS No. VA-74

HABS
VA
80-Simo,
1-

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
District of Richmond, Va.

Historic American Buildings Survey
Major Eugene Bradbury, District Officer
210 East Franklin St., Richmond, Va.

HABS
VA

80 Simonson

1-

INDIAN BANKS
Simonson, Virginia

Owner: Robert Gamble

Date of Erection: c.1700

Architect:

Builder:

Present Condition: Good

Number of Stories:

Materials of Construction: Brick

Other Existing Records: None known

Additional Data:

—JLW
Dec. 29. 3